

**Dickerson, Dave**

---

**From:** Dickerson, Dave  
**Sent:** Monday, March 06, 2017 1:37 PM  
**To:** ellen.iorio; 'Wolf, Steven H CIV USARMY CENAE (US)'; 'Morris, Mike (Bourne)'; anita.rigassio-smith; 'Wolf, Steven H CIV USARMY CENAE (US)'; Lederer, Dave  
**Cc:** Catri, Cindy  
**Subject:** EPA comments on Aerovox tech memo figures

Ellen and all - here are my comments on the subject figures. Overall nicely done!

1. All Figures showing Cross-Section A-A' and B-B' (Figures 2-3, 2-4, 3-1, 3-3, 3-10 and 3-11): suggest adding the labels "North Trench", "South Trench" and "Storm Drain Pipe" along the top of the cross-section at the respective location for each of these three features.
2. All Figures showing "Bathy Elevation" in the Legend: change to "Bathymetric Elevation" and add the year in which the bathy was taken.
3. Figures 2-3 through 2-9: the color-coding indicating the PCB data type (IA, Congener or Aroclor) is different than that used in Figures 3-3 through 3-9. For clarity recommend changing this color-coding in Figures 2-3 through 2-9 to match that used in Figures 3-3 through 3-9.

Any questions please let me know.

Dave D.

David J. Dickerson  
Remedial Project Manager  
USEPA - Region 1  
OSRR07-4  
5 Post Office Square  
Boston, MA 02109-3912  
617 918 1329